

Staff Report and Recommendations Agenda of November 24, 2025, Item 6a

COUNTY of VENTURA County of Ventura • Resource Management Agency

800 S. Victoria Avenue, Ventura, CA 93009-1740 • (805) 654-2478 • www.vcrma.org/divisions/planning

I. <u>APPLICANT/PROPERTY OWNER:</u>

Applicant: Tod Stockwell, Principal

T Stock Design Studio 1740 Mountain Avenue Santa Barbara, CA 93101

Property Owner: Glenn Sutherland

127 Santo Tomas Ln Montecito, CA 93108

II. REQUEST:

A request for a Certificate of Appropriateness for the installation of aluminum-clad windows on high-visibility building elevations and after-the-fact authorization of remaining vinyl windows at a 12-unit apartment complex located at 534-542 S. F Street, Oxnard, CA 93030 (Ventura County Landmark #173: McColm Manor Apartments). The scope of work also includes the construction of a pergola at the front entrance to the property. (Case No. CH23-0040).

III. LOCATION AND PROPERTY INFORMATION:

534-542 S. F Street, Oxnard, CA 93030

Assessor's Parcel Number (APN): 202-0-121-080 Historic Designation: Ventura County Landmark #173 Common/Historic Name: McColm Manor Apartments

The subject property consists of a 12-unit, two-story courtyard complex with detached garage buildings. The property is known as a fine example of a 1950 "u-parti" form of courtyard apartment complex in the City of Oxnard and has an active Mills Act Historical Property Contract.

IV. PROJECT SCOPE:

The proposed scope of work consists of the installation of aluminum-clad windows on high-visibility building elevations and after-the-fact authorization of remaining vinyl windows at a 12-unit apartment complex located at 534-542 S. F Street, Oxnard, CA 93030. The scope of work also includes the construction of a pergola at the front entrance to the property, which is one remaining work item from the adopted Mills Act contract for the property. Refer to Exhibit 1 for a site plan and elevations, including current photos of the apartment building.

_

San Buenaventura Research Associates, 534-42 S. F Street Determination of Eligibility for Designation as a City of Oxnard Historic Landmark, October 11, 2013.

In 2022, the current property owner replaced all of the remaining original light steel casement windows with vinyl clad windows without permit authorization, which triggered a City of Oxnard violation case and code enforcement actions. According to the property owner, the previous windows were deteriorated and partially inoperable.

V. <u>SUMMARY OF PREVIOUS CHB HEARINGS</u>

This item was previously reviewed by the CHB at their hearing on November 13, 2023. At that time, a consensus of CHB members favored replacing the vinyl windows, in whole or in part, with a more appropriate window product. The property owner's architect indicated a willingness to identify a suitable replacement window for the vinyl windows, one that would retain more of the historical design, color, texture, and other visual qualities of what existed previously. The CHB took no action on the request and continued the item to a future date uncertain. Following this meeting, Board Members Blum and Fernandez accompanied the property owner's architect to a window store to identify a suitable replacement window.

Upon confirmation of the applicant's proposed scope of work, the item was again reviewed by the CHB at their hearing on October 13, 2025. At that time, the property owner indicated that he no longer intended to replace the vinyl windows with a suitable replacement and instead requested after-the-fact authorization of the vinyl windows as-is. A consensus of CHB members again favored replacing the vinyl windows, in whole or in part, and the property owner agreed to develop a window replacement schedule for those windows on highly visible building elevations for the CHB's future review. The CHB took no action on the request and continued the item until their hearing on October 27, 2025.

Following this hearing, due to ongoing enforcement issues at this site, City of Oxnard staff determined that it was necessary for the window replacement schedule to show all window replacement work would be completed no later than December 31, 2026.

The property owner did not attend the scheduled CHB hearing on October 27, 2025, so the applicant representing the property owner answered questions and requested more time to discuss the window replacement timeline with the property owner. At the October 27, 2025, hearing, the CHB discussed the location of windows to be replaced and requested more details on the proposed window types. Daniel Houck, City staff, confirmed that City staff is looking for a recommendation from the CHB as to which windows should be replaced. Then, City staff would track the property owner's progress and potentially pursue either option (non-renewal or cancellation) as necessary. The CHB took no action on the request and continued the item until their hearing on November 24, 2025.

VI. SIGNIFICANCE AND BACKGROUND:

The McColm Manor Apartments were evaluated for historical significance by San Buenaventura Research Associates in October 2013 (Exhibit 2). Based on the historic resources evaluation, the property was found eligible for Ventura County Landmark designation under Criteria 1 (it exemplifies or reflects special elements of the County's architectural history) and 4 (it embodies elements of architectural design, details, materials or craftsmanship which represents a significant structural or architectural achievement or innovation). The property was designated as Ventura County Landmark #173 on December 8, 2014. A Mills Act Historical Property Contract was approved for the property on December 2, 2014 (Exhibit 3).

Historical Background

The Town of Oxnard was laid out in 1898 on the lands of John G. and Aranetta Hill. It was primarily a neighborhood of single family homes during the early years. The Hill Residence, located west of the subject property, was built in the 1870s on a 630 acre ranch owned by John G. and Aranetta Hill.² The Hills arrived in Ventura County in 1868 and purchased land from Thomas Scott, owner of Rancho El Rio de Santa Clara. John G. Hill died in 1904. It is believed his wife Aranetta died in 1925, the same year that the Eastwood-Lathrop Subdivision was recorded and opened on the former lands of the Hill property, just south and west of the boundaries of the Town of Oxnard. The boundaries of the subdivision are Fifth Street on the north, Seventh Street on the south, G Street on the west and E Street on the east.³

With the 1920s housing boom, multifamily housing units began to make an appearance, primarily in the form of courtyard housing. Between 1920 and 1950 approximately fifteen such properties were developed throughout the city. As of 2013, only about seven were known to remain.⁴ The 12-unit courtyard housing complex at 534-542 South F Street known as McColm Manor was completed in 1950 for Ralph C. and Sofia McColm. Ralph Carter McColm was born in Kansas in 1893, practiced as a chiropractor in Washington in the late 1920s, and moved to Southern California with his wife in the late 1940s. They lived in Ojai and Santa Barbara and invested heavily in real estate and real estate development around Ventura County. In late 1949, they purchased two adjacent parcels in the Eastwood and Lathrop Subdivision from Edgar and Martha Johnson. The property was owned by the McColm family until at least the 1970s.⁵

Architectural Background

² Ibid.

³ Ibid.

⁴ Ibid.

⁵ Ibid.

The property is an example of the "u-parti" form of courtyard apartment complex construction. One of the most common and characteristic of the courtyard types built in Southern California, the u-parti is defined by building masses enclosing a courtyard on three sides with an opening facing the street. The courtyard in this housing type is often "completed with a thin wall screen connecting the two front bars of the U," a detail seen in this property.⁶

The buildings' style is Minimal Traditional, a popularized form of the Modern style that incorporates familiar design elements derived from historical architectural styles into otherwise Modern buildings. The low-pitched, hipped roof, boxed eaves and faux shutters seen on this property are representative of this approach. The designer of the courtyard apartment complex is undocumented. The buildings were constructed by the Bergseid Construction Company, a large and prolific Ventura-based contracting firm. The apartments of McColm Manor provided housing to a variety of working-class Oxnard residents. The one-bedroom units were apparently mostly rented to single residents, with a particular emphasis on the professions populating Ventura County during the immediate postwar period. Residents during the 1950s included members of the military, teachers, and nurses.

The property consists of two, two-story apartment buildings and two single-story garage buildings. The two residential buildings have L-shaped plans and are arranged symmetrically on the site. Together with the brick wall at the front (west side) of the property, a U-plan courtyard apartment complex is formed. The residential buildings feature low-hipped roofs with shallow boxed eaves. The windows previously consisted of pairs of four-by-one light steel casements and tripartite four-by-one light casements with transoms over, with shallow sills and no framing. There are also window openings at the street-facing elevation filled with six-by-five glass block. All of the street-facing windows feature single, louvered, faux shutters on one side of the window opening. These faux shutters appear to be original to the building and were identified as a character-defining feature of the property. Ground floor entries are located above low concrete stoops. Second floor entries are accessed via stairways leading to common balconies. There are wood frame pergolas supported by pipe columns over the balconies. The pergolas are currently covered with clear corrugated panels. The stairways feature stucco balustrades topped with steel pipe handrails.⁹

Two single-story, 3-bay garages are oriented towards the alley to the rear (east side) of the property. The garages are also stucco-clad with hipped roofs. There is a grass lawn in the central courtyard as well as a grass lawn separating the buildings and walls from the sidewalk. There are many low foundation plantings and shrubs both within

⁶ Ibid.

⁷ Ibid.

⁸ Ibid.

⁹ Ibid.

Cultural Heritage Board Staff Report – Item 6a Case No. CH23-0040 November 24, 2025 Page 5 of 14

and outside of the courtyard. Several mature palm trees are located between the apartment complex and the sidewalk.¹⁰ A pergola was previously located over the courtyard entrance.

Alterations/Changes

At the time of evaluation in 2013, the interior of the apartment complex retained original cabinets and tile counters in the kitchen and bathrooms, as well as original flooring (of unknown wood type and condition) beneath the contemporary laminate flooring. In addition, the exterior of the courtyard apartment was found to retain substantial integrity although some changes are known to have occurred, consisting of the following:¹¹

- A couple of the exterior shutters have been replaced with similar (vinyl) but not identical types;
- The low brick planters at either side of the entry walkway have been modified to create brick pilasters;
- A freestanding pergola originally located over the entry to the courtyard has been removed;
- A two-story, grid-like, wood screen between the apartment buildings at the rear of the courtyard has been removed;
- The landscaping has changed over time; and
- Plastic corrugated sheets added to the top of the second story balconies' wood frame pergolas.

In 2022, the current property owner replaced all of the remaining original light steel casement windows with vinyl clad windows. Figure 1, below, shows the apartment complex with the new windows. This alteration removed a key character-defining feature¹² and appears to have substantially reduced the historic integrity of the property. The property owner has applied for the phased installation of aluminum-clad windows over a period of five years and after-the-fact authorization of some vinyl-clad windows. Refer to Figure 2 and Figure 3 below for views of the subject property prior to this alteration. Exhibit 4 conditions additional photos of the property's current condition.

¹⁰ Ibid.

¹¹ Ibid.

Defined as "the physical aspects of a site's design and form which identify it as belonging to a specific time and place. Design, materials, workmanship, form, and style of decorative and structural features and spaces, and spacial relationships both interior, exterior, and environmental. A building, for example, may have character-defining features that include, but are not limited to, the overall shape, massing and form of the building, its roof and roof structures, openings, projections, trim, materials, craftsmanship, decorative details, as well as the various aspects of its site, landscape, and environment."

Figure 1 – View of property in 2023 following window alteration (looking east)



Figure 2 – View of property in 2020 prior to window alteration (looking southeast)




Figure 3 – View of property's central walkway in 2020 prior to window alteration (looking east)



Mills Act Contract

A Mills Act Historical Property Contract between the property owner and the City of Oxnard was approved for the property on December 2, 2014 (Exhibit 3). The contract is binding to the property and inherited by any subsequent owners, including the current property owner. As part of the contract, the owner agreed to preserve, restore, and rehabilitate the property in conformance with the Secretary of the Interior's Standards for the Treatment of Historic Properties with Guidelines for Preserving, Rehabilitating, Restoring, and Reconstructing Historic Buildings ("Secretary of the Interior's Standards"), among other requirements. Based on the most recent staff inspection of the property on March 11, 2020, staff found that rehabilitation work outlined in the contract's Ten-Year Rehabilitation remained, in whole or in part, for Years 4, 7, 8, and 10 (Exhibit 3). Self-certification materials submitted in subsequent years showed that Year 7 and Year 8 items were also completed. Remaining items to be accomplished include building a pergola over the courtyard entrance to restore it to its original condition and re-roofing all four buildings, the apartments buildings and garages. Refer to Figure 4 for a historical photo showing the original wall configuration, pergola, screen, and faux window shutters.





Source: San Buenaventura Research Associates

In exchange for reduced annual property taxes with the adopted Mills Act contract, the property owner agrees to preserve, restore, and rehabilitate the subject property according to the *Secretary of the Interior's Standards*. The City of Oxnard may cancel the contract and impose financial penalties if it determines the owner has failed to restore or rehabilitate the property in the manner specified in the contract.

VII. CULTURAL HERITAGE ORDINANCE ANALYSIS:

The scope of work requires a Certificate of Appropriateness (COA) from the CHB. Ventura County Cultural Heritage Ordinance (Ordinance) §1371-4 provides that the CHB uses the *Secretary of the Interior's Standards* in its evaluation of the property and the proposed scope of work. CHB staff determined the standards for rehabilitation are appropriate for this request and evaluated the scope of work against the relevant standards below.

Using the Secretary of the Interior's Standards as a guide, the CHB shall approve the COA for any proposed work on the site if one of the standards identified in Ordinance §1371-4 can be met. The relevant standard for this request is that the work will neither reduce the significant architectural features nor reduce the character of historical, architectural, or aesthetic interest or value of the site. Pursuant to Ordinance §1371-

4(d), the COA may be approved if the applicant presents facts and clear evidence, as described therein, demonstrating that failure to approve the request for a COA will cause a hardship because of conditions peculiar to the structure or other feature involved, or damage to the property owner is unreasonable in comparison to the benefit conferred to the community.

Standards	Staff Comments
#1. A property will be used as it was historically or be given a new use that requires minimal change to its	The property will continue to be used as a multifamily residence.
distinctive materials, features, spaces, and spatial relationships.	Staff determined that this Standard has been met.
#2. The historic character of a property will be retained and preserved. The removal of distinctive materials or alteration of features, spaces, and spatial relationships that characterize a property will be avoided.	The Secretary of the Interior's Standards ¹³ encourage the retention of historic features that contribute to the interpretation of the significance of a historic property and, when appropriate, repair of materials and limited replacement of deteriorated or missing parts rather than full replacement.
	It would have been preferable to retain the steel casement windows to assess the feasibility of repairing rather than replacing this key character-defining feature. Based on photographic evidence, it is not clear that replacement was a suitable treatment as opposed to retaining and repairing the windows, including restoring mechanical functionality, repainting muntins, and replacing glazing as needed. Moreover, vinyl windows are not a suitable replacement and do not match the previous windows in terms of design, color, texture, materials, and other visual qualities. This alteration appears to have substantially reduced the historic integrity of the property.
	However, the applicant now proposes replacing nearly all highly visible vinyl windows on the building's primary elevations with a more appropriate aluminum-clad window product, which would reduce the previous loss of integrity.
	Staff determined that this Standard has been partially met.

Weeks, Kay D., The Secretary of the Interior's Standards for the Treatment of Historic Properties: with Guidelines for Preserving, Rehabilitating, Restoring & Reconstructing Historic Buildings, U.S. Department of the Interior, National Park Service, revised 2017, pg. 140.

Standards	Staff Comments
#3. Each property will be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical development, such as adding conjectural features or elements from other historic properties, will not be undertaken. #4. Changes to a property that have acquired historic significance in their own right will be retained and	It does not appear that conjectural design features from other historic properties or inappropriate time periods are proposed to be added to the property with the intent of creating a false sense of historical development. Staff determined that this Standard has been met. There do not appear to be changes to the property that have acquired historic significance in their own right.
#5. Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a property will be preserved.	Staff determined that this Standard has been met. The steel casement windows that were removed were a key character-defining feature of the subject property. This appears to have substantially reduced the historic integrity of the property. However, the applicant now proposes replacing nearly all highly visible vinyl windows on the building's primary elevations with a more appropriate aluminum-clad window product, which would reduce the previous loss of integrity.
#6. Deteriorated historic features will be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature will match the old in design, color, texture and, where possible, materials. Replacement of missing features will be substantiated by documentary and physical evidence.	Staff determined that this Standard has been partially met. As mentioned previously, it would have been preferable to retain the steel casement windows to assess the feasibility of repairing rather than replacing this key character-defining feature. Based on photographic evidence, it is not clear that replacement was a suitable treatment as opposed to retaining and repairing the windows, including restoring mechanical functionality, repainting muntins, and replacing glazing as needed. Moreover, vinyl windows are not a suitable replacement and do not match the previous windows in terms of design, color, texture, materials, and other visual qualities. This alteration appears to have substantially reduced the historic integrity of the property. However, the applicant now proposes replacing nearly all highly visible vinyl-clad windows on the building's primary elevations with a more appropriate aluminum-clad window product, which would reduce the previous loss of integrity. Staff determined that this Standard has been partially met.

Standards	Staff Comments
#7. Chemical or physical treatments, if appropriate, will be undertaken using the gentlest means possible. Treatments that cause damage to historic materials will not be used.	Not Applicable.
#8. Archeological resources will be protected and preserved in place. If such resources must be disturbed, mitigation measures will be undertaken.	Not Applicable.
#9. New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportion, and massing to protect the integrity of the property and its environment.	Window replacements, if determined appropriate, shall match the historic in terms of configuration, materials, details, and finish. The vinyl-clad windows are not a suitable replacement and do not match the previous windows in terms of design, color, texture, materials, and other visual qualities. This alteration appears to have substantially reduced the historic integrity of the property. However, the applicant now proposes replacing nearly all highly visible vinyl windows on the building's primary elevations with a more appropriate aluminum-clad window product, which would more closely match the original windows and reduce the previous loss of integrity.
#10. New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.	Staff determined that this Standard has been partially met. Integrity is defined as the ability of a property to convey its historical significance, or the authenticity of a property's historic identity, evidenced by the survival of physical characteristics and materials that existed during the property's historic or prehistoric period of significance. A property would typically possess several (although not necessarily all) of the following seven aspects of integrity, as defined in National Register Bulletin 15, to convey its significance: Location, Design, Setting, Materials, Workmanship, Feeling, and Association. ¹⁴
	The window replacements appear to maintain the same opening locations and dimensions as existed historically. Therefore, if replaced or removed in the future, the essential form and integrity of the historic property and its environment would appear to be unimpaired.

Standards	Staff Comments
	Based on the above considerations, staff determined that this Standard has been met.

VIII. STAFF CONCLUSION:

Based on the above considerations, the scope of work appears partially consistent with the *Secretary of the Interior's Standards*. It would have been preferable to retain the steel casement windows to assess the feasibility of repairing rather than replacing this key character-defining feature. Based on photographic evidence, it is not clear that replacement was a suitable treatment as opposed to retaining and repairing the windows, including restoring mechanical functionality, repainting muntins, and replacing glazing as needed. Moreover, vinyl windows are not a suitable replacement and do not match the previous windows in terms of design, color, texture, materials, and other visual qualities. This alteration appears to have substantially reduced the historic integrity of the property.

Following the CHB hearing on October 13, 2025, the applicant now proposes replacing nearly all highly visible vinyl windows on the building's primary elevations (the west elevation adjacent to F Street, and part of the north and south elevations closest to F Street) with a more appropriate aluminum-clad window product, which would more closely match the original windows in appearance and reduce the previous loss of integrity.

As this site is governed by a Mills Act Contract with the City of Oxnard, City staff has been pursuing the property owner for code enforcement violations that include the unpermitted windows and non-compliance with the approved 10-year rehabilitation plan approved by the Oxnard City Council. City staff and the property owner are not currently in agreement and will likely need to continue working through issues related to the Mills Act Contract and the timing of violation abatement. To help inform this discussion, your Board is being asked to provide a determination, based on the Secretary of the Interior's Standards, on which windows are to be replaced at the site and the appropriate window type and material. Questions on the timing or phasing of window replacement fall outside the purview of the Cultural Heritage Board and will be determined through future negotiations between the property owner and City staff.

In addition, City of Oxnard staff shared that new building code energy efficiency requirements may preclude the ability of the City to approve the existing vinyl windows on an after-the-fact basis. The property owner's representative was informed of this possibility. This will be determined at the building permit review stage and may lead to additional window replacements at the site.

Further, the applicant proposes construction of a pergola at the property's primary entrance to satisfy a remaining Mills Act contract requirement. The proposed design of the pergola matches that which existed on the site previously and is compatible with the Secretary of the Interior's Standards.

Based on the above, CHB staff recommends the CHB adopt the below recommendation related to the scope of work in order to better conform to the Secretary of the Interior's Standards.

Recommendation #1: Replacement Windows. Due to their visibility from the
vicinity of the property, it is recommended that all windows on the north and
south elevations, along with the second-story windows on the east elevation,
also be replaced.

If the applicant does not agree with the CHB's adopted recommendation(s) and incorporate them into the project, CHB staff does not believe that the required findings to approve the Certificate of Appropriateness can be made (Cultural Heritage Ordinance §1371).

As mentioned previously, as part of the adopted Mills Act contract, the property owner agrees to preserve, restore, and rehabilitate the subject property according to the *Secretary of the Interior's Standards*. As noted above, the City of Oxnard may cancel the Mills Act contract and impose financial penalties if it determines the owner has failed to restore or rehabilitate the property in the manner specified in the contract. The City of Oxnard staff is solely responsible for enforcing the terms of the Mills Act contract.

IX. OPPORTUNITY TO SHOW HARDSHIP:

At the CHB public hearing on this matter, if desired, the property owner is provided with the opportunity to present facts and evidence demonstrating a failure to grant the requested Certificate of Appropriateness would cause an economic hardship as provided by Ordinance Section 1371-4(d).

X. PUBLIC COMMENTS:

No public comment regarding this item has been received to date.

XI. RECOMMENDED ACTIONS:

CHB staff recommends the CHB take the following actions regarding the request:

 CONDUCT public hearing, RECEIVE oral and written testimony, and CONSIDER the CHB staff report and all exhibits and attachments hereto;

- 2. **FIND** that the proposed project meets the requirements of the Ventura County Cultural Heritage Ordinance §1371-4; and
- 3. Based on the preceding evidence and analysis, APPROVE the Certificate of Appropriateness (Ordinance Section 1371) with any project modification(s) determined necessary to conform to the Secretary of the Interior's Standards and Ordinance Section 1371-4.

Reviewed by:

Tricia Maier, Manager

(805) 654-2464

Planning Programs Section

Prepared by:

Dillan Murray, Senior Planner Ventura County Planning Division (805) 654-5042

Exhibits:

Exhibit 1: Site Plan and Elevations

DPR Form 523, October 11, 2013 Exhibit 2:

Exhibit 3: Mills Act Contract

Exhibit 4: Supplemental Photos