

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

EDGINGTON OIL REFINERY
3450 East Fifth Street
Oxnard
Ventura County
California

HAER CA-2384


INDEX TO BLACK AND WHITE PHOTOGRAPHS

Photography by Tavo Olmos, Positive Image Photographic Services, June 2022

- Photo 1 Contextual view of oil derrick with adjacent storage tanks from the southeastern portion of the site looking west.
- Photo 2 Detail view of oil derrick with adjacent storage tanks from the southeastern portion of the site looking west.
- Photo 3 View of water tank and tank numbers 2011 and 2012 looking northwest.
- Photo 4 Detail view of water tank looking northwest.
- Photo 5 View of oil derrick and storage tank number 30001 from southern portion of site looking northwest.
- Photo 6 Detail view of oil derrick looking north.
- Photo 7 View of oil derrick and storage tank 12001 from southern portion of site looking north.
- Photo 8 View of oil derrick and adjacent storage tanks from southern portion of site looking north.
- Photo 9 Detail view of oil derrick and storage tank numbers 2005, 2006 and 3502 looking northeast.
- Photo 10 Detail view of oil pumping equipment “El Rio #2” looking north.
- Photo 11 Detail view of oil derrick looking up.
- Photo 12 View of oil derrick and portion of storage tank number 12001 looking west.

- Photo 13 Close up view of storage tanks numbers 12001 and 506 looking northeast.
- Photo 14 Contextual view of storage tanks in the mid-section of site looking north-northeast.
- Photo 15 View of storage tank numbers 701, 702, 1501 and 1503 looking southeast.
- Photo 16 Contextual view of oil derrick and adjacent storage tanks from atop tank number 2003 looking southwest.
- Photo 17 Contextual view of storage tanks from atop tank number 2003 looking southeast.
- Photo 18 Contextual view of storage tank numbers 1004, 2007 and 701 looking east.
- Photo 19 View of oil derrick with storage tank numbers 12001, 701, 1503, 1501 and 3502 looking south.
- Photo 20 View of oil derrick from the northwest portion of the site showing storage tank number 12001,
- Photo 21 Detail view of oil pumping equipment in the mid-eastern portion of the site looking southwest.
- Photo 22 Contextual view of site from north side of East Fifth Street showing lab, storage tanks and oil derrick looking southeast.

EDGINGTON OIL REFINERY
3450 EAST FIFTH STREET
OXNARD, VENTURA COUNTY, CA
HAER CA-2384





Kodak 100T MX

10000000

10000000





Kodak 100TMAX



Kodak 100T MX



KODAK 100T MX

A 0 0 0 0 0 0

0 0 0 0 0 0

00000000

00000000



00000000



Kodak 100T MX







CALIFORNIA
RESOURCES CORPORATION
EL RIO #2
SEC. T. /R.
In Case of Emergency Please Call: (916) 705-6803



Kodak 100T MX



13542010

13542010



Kodak 100TMX

13542010

13542010



Kodak 100T MX



Kodak 100T MX




005
9-19-19

T-263

005

KODAK SAFETY FILM



Kodak 100T MX



Kodak 100TMAX



Kodak 100T MX



Kodak 100T MX





Kodak 100T MX











































